

This diagram illustrates the assembly of a 500W motor. It features an exploded view of the main components, including the motor housing, stator, rotor, and various internal parts like bearings, seals, and screws. Each part is labeled with a number, and arrows indicate the assembly sequence. Key dimensions are provided for the motor housing, such as 186.5, 101, 79.5, 82.6, 41.3, 20.65, 8.55, 9.5, and 57. A note specifies '9.5 profondità 5mm' (9.5 depth 5mm) for the shaft. The diagram also includes a section for the 'KIT GUARNIZIONI-TENUTE-O RING' (KIT GASKETS-SEALS-O RING) and a container of 'GRASSO GREASE' (gr. 100). The final assembly is shown in three different configurations, labeled 1, 2, and 3, with corresponding part numbers like 130, 132, 129, 68, 69, and 131.